



MID-STATE ASSOCIATES, INC.

3-15-6
34-16-6

1230 South Blvd.
Baraboo, Wisconsin
53913
608-356-8344

Engineers • Architects • Planners • Surveyors

April 24, 1985
999700

Kiedrowski Engineering, Inc.
4340 80th Street South
Wisconsin Rapids, Wisconsin 54494

Re: Town Line Between T15N,T6E & T16N,T6E

Dear Tony:

After thoroughly reviewing this matter which we discussed last Saturday, I am of the firm opinion that the monuments should stay where they were placed. Back in July of 1978, you and I met on this matter and mutually agreed as to where these corners should be placed.

Recently you uncovered a stone at the purported northeast corner of Section 3, T15N,R6E. Undoubtly, this was placed by M.C. Smith with little regard to proper procedures as outlined by survey law.

By using the straight line method as we did in 1978, the north one-quarter corner of Section 3 fits within reason to the call made for going by the 50 foot high bluff to the south by 20 links in the original notes.

If you were to accept M.C. Smith's erroneous corner, this would not fit as well and it would shorten up the southern one-half mile in Section 34, T16N,R6E by about 200 feet. This is unheard of along with the tremendous kink you would be putting in the town line. M.C. Smith's corner which you found has no more credence than a corner set by Jim Carroll using similar methods. I can unequivocally state the Smith's stone is not in the position of the original survey monument.

Sincerely,

MID-STATE ASSOCIATES, INC.

Frederic W. Zietlow, R.L.S.

FWZ/1a

cc: Gregory Rhinehart, Adams County Surveyor

MIS 34160600001