CORNER NO. ADAMS COUNTY SECTION Survey Monument Record 17 N TOWN TYPE OF MONUMENT: PK Nail in Asphalt over Concrete RANGE STATE PLANE COORDINATES: N. ELEVATION - M.S.L. DATUM: -THETA ANGLE: __ FIELD BOOK: _ BASIS FOR MONUMENT LOCATION (Use reverse side if necessary) LOCATION Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. Re-established Quarter corner by retracement of Warner and McConick-Subdivision, and checking into Homewood Subdivision. Did not attempt excavation because corner falls in State Truck Highway 13, which has a concrete base. CERTIFIED CORRECT: Registered Land Surveyor Outside corner TIE SKETCH HOUSE (Show at least four ties) Concrete Sign Foundation 3/4" Square Bar 1" Iron Pipe Can't find Nail 9 878 disa HOUSE

Top corner

REVISED 1974

mis08170600003