

DESCRIPTION of Section, Quarter Section and Quarter quarter Section Corners of Section

Township _____ North, Range _____ East of _____ Principal Meridian.

N. B. - The variation of needle adopted in establishing corners is _____

No.	Government Corners.	Bearing Trees.	In. dia.	Courses they bear.	Links Distant.	Bearing Trees.	In. dia.	Courses they bear.	Links Distant.
1	N. W. Sec. cor. Identified								
2	N. E. Sec. cor. Identified								
3	S. E. Sec. cor. Identified								
4	S. W. Sec. cor. Identified								
5	N. 1/4 Sec. cor. Identified								
6	E. 1/4 Sec. cor. Identified								
7	S. 1/4 Sec. cor. Identified								
8	W. 1/4 Sec. cor. Identified								
<p style="text-align: center;"><i>new Blk oak 12 S-60-E 57</i></p>									
NO. SUBDIVISION CORNERS.									
1	Center 1/4 Sec. cor.								
2	North 1/4-1/4s N. W. qr.								
3	East 1/4-1/4s N. W. qr.								
4	South 1/4-1/4s N. W. qr.								
5	West 1/4-1/4s N. W. qr.								
6	Center 1/4-1/4s N. W. qr.								
7	North 1/4-1/4s N. E. qr.								
8	East 1/4-1/4s N. E. qr.								
9	South 1/4-1/4s N. E. qr.								
10	Center 1/4-1/4s N. E. qr.								
11	East 1/4-1/4s S. E. qr.								
12	South 1/4-1/4s S. E. qr.								
13	West 1/4-1/4s S. E. qr.								
14	Center 1/4-1/4s S. E. qr.								
15	South 1/4-1/4s S. W. qr.								
16	West 1/4-1/4s S. W. qr.								
17	Center 1/4-1/4s S. W. qr.								

NAMES OF SWORN ASSISTANTS.

CHAINMEN.	FLAGMEN.	AXMEN.
<i>Arthur Pells</i> <i>Wm. M. Smith</i>		

MINUTES.

Starting at the Identified quarter Post on east side of section 10 T18 R7 E and run south at 5-D-V 40 chains & 30 links to the Identified south East corner of said section. Then from the Established 3rd Post on east side of section Run west on 3rd line 80 chains to the Established 2nd Post on west side of section. Then south on section line on west side of section 20 chains & found Post and found 2. 2nd stump which was correct as to distance & course for bearing stumps. was satisfied that the true corner was found. Then from the Established 2nd Post on west side of section Run west 20 chains & set Post. said line was because the down Road had built a Highway on this line, said Highway was about 3 rods too far south on west East, made one new Bearing at quarter Post on east side of section as shown above.

Wm. M. Smith County Surveyor

M1510180700001