

34
SECTION

19
TOWN

05
RANGE

ADAMS COUNTY

COUNTY CORNER NO: 118

ROMPORTOL ID: 41905342000

PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT: HARRISON (BROKEN-TOP)
ADAMS COUNTY COORDINATES, NAD 83 (2005)

N. 258442.106

E. 514988.456

ELEVATION- _____ DATUM _____


FIELD WORK DATE: 11/11/2019

BASIS FOR MONUMENT LOCATION

1980 - PLS 1478 SET A HARRISON MONUMENT EQUIDISTANT AND ON LINE BETWEEN ADJACENT SECTION CORNERS.


2014 - PLS 2443 FOUND HARRISON MONUMENT AND ESTABLISHED REFERENCE TIES TO PERPETUATE THE CORNER LOCATION.

2019 - PLS 2675 FOUND HARRISON (BROKEN-TOP) MONUMENT 6"± BELOW THE ROAD SURFACE (18"± UNDER WATER) AND 1 GOOD TIE (SW WAS BENT). ALL WITNESSES HAVE BEEN DESTROYED BY LOGGING AND FIELD CLEARING. THE NE TIE FIT WELL WITH THE MONUMENT. ACCEPTED THE HARRISON (BROKEN-TOP) MONUMENT AS THE CORNER LOCATION. SET 2 NEW TIES, STRAIGHTENED THE SW TIE AND MEASURED TO THE EXISTING TIES.



LOCATION
(INDICATE CORNER BY "X")

SEAL:




DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

DATE 11/1/2020

- TIE SKETCH

NOTE: THE CORNER FALLS 2'± EAST OF 16TH AVE CENTERLINE.



- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- FOUND 3/4" IRON ROD
- ⊕ FOUND HARRISON (BROKEN-TOP) MONUMENT
- VINYL "T" POST


Government Land Corner Certificate

HAR. SET
4/23/80
RM-SS

RR 5

ADAMS County
 TYPE OF MONUMENT: HARRISON STANDARD
 STATE PLANE COORDINATES: N _____ E _____
 ELEVATION — M.S.L. DATUM: _____
 THETA ANGLE: _____
 FIELD BOOK: 83 PAGE 60
 DRAWN BY: G. RHINEHART

CORNER NO. 118
 SECTION 35
 TOWN 19
 RANGE 5



LOCATION
(Indicated by 'X')

SEAL:



DATA SHOWN HERE ON
CERTIFIED CORRECT:

Gregory P. Rhinehart
Registered Land Surveyor

DATE: 1/21/80

BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary)

Set corner equidistant and on line between adjacent section corners. No evidence of any previous monumentation was found while excavating with backhoe. No record of any monumentation subsequent to the original was found.

- 1 new 3-21-84 SS
- OK 11-22-88 G.R.-J.R.
- OK 2-14-94 CR-JG
- 2-NEW, MON. OK, 2-10-98-JG
- 1-GONE, 4-LEFT, 1-02-03-JG

3 NEW TIES 4-6-09-SS

TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.

