SECTION

OB ADAMS COUNTY

COUNTY CORNER NO: 120

ROMPORTOL ID: 41906362000


PUBLIC LAND SURVEY MONUMENT RECORD

HARRISON TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007) N. **258626.217** E. 557196.249 ELEVATION-DATUM FIELD WORK DATE: 01/29/2018


BASIS FOR MONUMENT LOCATION

1977 - PLS 1103 RAN EDM/T2 TRAVERSE ALONG THE RANGE LINE FROM THE SOUTHWEST CORNER OF SECTION 31-19-7 TO THE NORTHWEST CORNER OF SECTION 18-19-7 TO DETERMINE THE SEARCH AREA FOR INVESTIGATION. FOUND NO EVIDENCE OF THE ORIGINAL CORNER OR ANY SUBSEQUENT RESURVEY MONUMENTATION. ALSO COULD NOT FIND ANY BEARING TREES. RELOCATED THE CORNER BY SINGLE PROPORTIONATE MEASUREMENT ON A LINE BETWEEN ADJACENT SECTION CORNERS. SET A HARRISON MONUMENT AT THE CALCULATED LOCATION AND TIED OUT.

2018 - PLS 2994 FOUND A HARRISON MONUMENT 2" ABOVE THE GROUND SURFACE. FOUND NO EVIDENCE OF ANY OF THE WITNESSES. ACCEPTED THE HARRISON MONUMENT AS THE BEST EVIDENCE OF THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE TIES.



LOCATION (INDICATE CORNER BY "X")





DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

- TIE SKETCH

NOTE: THE CORNER FALLS 35'± SOUTHEAST OF THE CENTERLINE OF THE TRAIL.





Government Land Corner Certificate

ADAMS	_County
TYPE OF MONUMENT: HARRISON	570.
STATE PLANE COORDINATES: N	
<u>F.</u>	
ELEVATION — M.S.L. DATUM:	· .
THETA ANGLE:	
FIELD BOOK: 54	PAGE24/
DRAWN BY: Scott SORENSEN	<u> </u>

SEAL:

BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary) Ran EDM/T2 traverse along range line from Southwest corner of Section 31-19-7 to Northwest corner of Section 18-19-7 to determine search area for investigation.

Could find no evidence of the original corner or any subsequent resurvey monumentation. Could find no bearing trees.

Relocated corner by single proportionate measure on line between adjacent section corners.

Set Harrison Monument on 8-31-1977.

114 CORNER NO. _ SECTION TOWN RANGE





DATA SHOWN HERE ON CERTIFIED CORRECT:

Registered Land Surveyor

11-2-197' DATE:

TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to NOTE at corner.

Ties in trees to nail in disc.

MAINTENANCE RECORD

Date	Init.	Remarks
7-17-92	GR	
2-26-02	56	OK
16-4-07	56/05	OK
		_

6"BLACK METAL POST DNOSIGN

REVISED 1977

HOARITE ADAMS COUNTY CORNER NO. SECTION Survey Monument Record TOWN TYPE OF MONUMENT: 2"x 30" IRON **RANGE** STATE PLANE COORDINATES: N_ ELEVATION - M.S.L. DATUM: THETA ANGLE: _ FIELD BOOK: ___ 30 BASIS FOR MONUMENT LOCATION (Use reverse side if necessary) Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner LOCATION (Indicated by 'X') SEAL: remarks, etc. Established center of Section 31 at intersection of Quarter Lines. S-1173 Wisconsi, Rapids,

CERTIFIED CORRECT:

Registered Land Surveyor

DATE: December 27, 1977

TIES OK MURZ 95 K Carlson

TIE SKETCH
(Show at least four ties)
NOTE

Ties in trees to nail in disc.

