SECTION

OF ADAMS COUNTY

COUNTY CORNER NO: 131

ROMPORTOL ID: 42005350000


PUBLIC LAND SURVEY MONUMENT RECORD

HARRISON TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007) N. **287549.322** E. 520283.635 ELEVATION- - - -DATUM - - -FIELD WORK DATE: 02/12/2018

BASIS FOR MONUMENT LOCATION

2015 - PLS 2452 FOUND A HARRISON MONUMENT 6" \pm BELOW GRADE OF THE ASPHALT ROAD PER TIE SHEET BY ANTHONY B. KIEDROWSKI, DATED 7-7-80. HE ALSO FOUND THE %" IRON ROD NORTHEASTERLY OF THE HARRISON MONUMENT AND THE %" IRON ROD SOUTHEASTERLY OF THE HARRISON MONUMENT. ACCEPTED THE HARRISON MONUMENT AND PLACED 2 ADDITIONAL TIES. DATE OF FIELD SURVEY & MONUMENT RECOVERY WAS SEPTEMBER 03, 2015.

2018 - PLS 2994 FOUND A HARRISON MONUMENT 12" BELOW THE ROAD SURFACE AND 4 TIES. THE MONUMENT AGREES WITH THE EXISTING TIES. ACCEPTED THE HARRISON MONUMENT AS THE CORNER LOCATION AND RE-MEASURED TO THE EXISTING TIES.



(INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR


3-1-18

- TIE SKETCH

NOTE: THE CORNER FALLS 2'± SOUTH OF THE CENTERLINE OF BADGER AVE AND 7'± EAST OF THE CENTERLINE OF 15TH AVE.



3/4" IRON ROD FOUND THARRISON FOUND ✓ STEEL FENCE POST VINYL "T" POST d atv sign




U.S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS: This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. Public Land Survey System.

= Corner monument restored.

SOUTHWEST CORNER OF SECTION 36, TOWNSHIP 20 NORTH, RANGE 05 EAST, TOWN OF ROME, ADAMS COUNTY, WISCONSIN





SEARINGS ARE REFERENCED TO THE WISCONSIN COUNTY COORDINATE SYSTEM, ADAMS COUNTY, WISCONSIN BEARINGS , THE WIS


SOUTH 1/4 Cor. 36-20-05.


(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence, or any other material evidence you considered, and whether the monument was found or placed.

I found a Harrison Monument $6"\pm$ below grade of asphalt road per tie sheet by Anthony B. Kiedrowski, dated, 7-7-80. I also found the $\frac{3}{4}"$ Iron Rod northeasterly of the Harrison Monument and the $\frac{3}{4}$ " Iron Rod southeasterly of the Harrison Monument. I accepted the Harrison Monument (see picture), and placed two (2) ties all as referenced below. Date of field survey & monument recovery was September 03, 2015. Elevations provided on section corners are based upon the NAVD88 Datum.

(c) In the plan view drawing below, provide reference ties to at least 4 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron, or other equally durable material.) Describe

(d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail





3/4"Ø SOLID IRON ROD FOUND NEXT TO STEEL "T" POST SEE TIE #2 PICTORY

(e) Describe any material discrepancy between the location of the corner as restored or re-established and the location of that corner as previously restored or re-established by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or re-established and (1) the corner as restored or re-established, and (2) to at least 2 of the 4 witness monuments shown on the drawing in (d), above.

No known discrepancy.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Found perpetuated location.

(g&h) Was the corner re-established through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

Found perpetuated location.

(i) I, Michael S. Marty, Professional Land Surveyor No. 2452, hereby certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

michal S. Marty Vierbicher Associates,Inc. Michael S. Marty, P.L.S. No. 2452

2105/55/19 Date

rerbicher olanners | engineers | advisors



FN: 150044 DATE: 09/22/2015 Drafted By: MMAR Checked By: MZIE

Affix Land Surveyor Seal 1111111111 NISCONS MICHAEL S. MARTY S-2452 NEW GLARUS WI SURV MINIMININ