OB ADAMS COUNTY

COUNTY CORNER NO: 5

ROMPORTOL ID: 42006059000

PUBLIC LAND SURVEY MONUMENT RECORD

HARRISON (BROKEN TOP) TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 321625.587

E. 535835.611


ELEVATION-DATUM

12/19/2016 FIELD WORK DATE:

BASIS FOR MONUMENT LOCATION

1974 - PLS 1103 EXCAVATED AN EXTESIVE AREA AND FOUND NO CONCLUSIVE EVIDENCE. SET CORNER PROPORTIONATELY IN THE EAST WEST DIRECTION AND ON LINE BETWEEN ADJACENT CORNERS.

2017 - PLS 2994 FOUND EXISTING HARRISON WITH A BROKEN TOP 18 INCHES BELOW THE ROAD SURFACE, ONE TIE AND ONE WITNESS TREE. THE HARRISON AGREES WITH THE EXISTING WITNESS TREE AND TIE. ACCEPTED HARRISON AND SET 4 NEW TIES.



LOCATION (INDICATE CORNER BY "X")

SEAL:

TIMOTHY RUTZEN. S-2994 DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

- TIE SKETCH



WOODS ADAMS COUNTY WOODS WOODS

● 3/4" x 18" IRON REBAR SET, 1.50#/FT ○ 1" OD IRON PIPE FOUND

HARRISON FOUND

VINYL "T" POST

WITNESS TREE FOUND

ADAMS COUNTY

Survey Monument Record

TYPE OF MONUMENT: HARRISON STANDARD

STATE PLANE COORDINATES: N

ELEVATION — M.S.L. DATUM:

THETA ANGLE: ______ PAGE _____

BASIS FOR MONUMENT LOCATION


(Use reverse side if necessary)

Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc.

Excavation and extensive search yielded no conclusive evidence. Set corner proportionately and on line between adjacent corners.

Note: This corner is set on the second standard parallel, and proportioned in the east and west direction from controlling monuments on that line.

1 new 5-11-84 SS-DK



SEAL:



O.K. 8-15-79 RN-RAK 1 NOW TIE 6-13-89 MK-SS OK 3-7-99 JG-GR OK 2-12-99-JG

CERTIFIED CORRECT:

Dale C. House

Registered Land Surveyor

DATE: 10-24-74

