SECTION

OB ADAMS COUNTY

COUNTY CORNER NO: 33

ROMPORTOL ID: 42006010000


PUBLIC LAND SURVEY MONUMENT RECORD

CALCULATED POSITION TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007) N. **314134.981** E. 557055.034 **ELEVATION-**DATUM — — — 02/06/2018 FIELD WORK DATE:

BASIS FOR MONUMENT LOCATION

1981 - PLS 878 NO RECORD OF ANY RESURVEYS. ANY MONUMENTATION WAS OBVIOUSLY DESTROYED DUE TO DITCHING. RAN EDM T-2 TRAVERSE OF SECTIONS 1 AND 12. ANALYZED FENCE AND POSSESSION LINES, COMPARED WITH ORIGINAL NOTES AND ARRIVED AT A LOCATION FOR THIS CORNER. A STRAIGHT-LINE PRORATION FOR THIS CORNER WOULD NOT HAVE FIT ANY POSSESSION LINES AT ALL. SET A HARRISON MONUMENT AT CALCULATED POSITION USING EVIDENCE AND TIED OUT.

2018 - PLS 2994 FOUND THE 3 EXISTING TIES FROM THE PRIOR TIESHEET. AFTER SEVERAL DIFFERENT METHODS OF CALCULATION WERE ATTEMPTED. THE CORNER WAS ESTABLISHED BY HOLDING A STRAIGHT LINE BETWEEN THE NW AND SE TIES AND USING THE RECORD DISTANCE FROM THE SE TIE (99.19'). IN DOING THIS THE TIE DISTANCE TO THE NW TIE IS 1'± LONG, BUT OTHER METHODS DID NOT AGREE WITH ADJACENT SECTION CORNERS. ACCEPTED THE CALCULATED CORNER POSITION AS THE BEST METHOD TO LOCATE THE CORNER. SET 1 NEW TIE AND MEASURED TO THE TIES.



RUTZEN, JR. S-2994 MOSINEE **WISCONSI** DATA SHOWN HERE ON THIS TIE SHEET IS

CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF


PROFESSIONAL LAND SURVEYOR


3-1-18 DATE

- TIE SKETCH

NOTE 1: THE CORNER FALLS IN THE MIDDLE OF THE DRAINAGE DITCH. NO MONUMENT WAS SET.

NOTE 2: FOR ACCESS, COME FROM THE NORTH OFF STH 73 THROUGH CRANBERRY FARM.





⊕ 1-1/4" O.D. IRON PIPE W/ALUMINUM CAP FOUND

3/4" x 18" IRON REBAR SET, 1.50#/FT

CALCULATED POSITION

→ VINYL "T" POST

	Government Land Corner Certificate	CORNER NO. 33
	ADAMS County	CECTION /
	TYPE OF MONUMENT: 3 / x24" IP + WITNESS CAPS	2.
1	STATE PLANE COORDINATES: N	70WIY
	E	RANGE
	ELEVATION — M.S.L. DATUM:	
	THETA ANGLE: FIELD BOOK: 86 PAGE 99	
	DRAWN BY: NJ	7
;		
	BASIS FOR MONUMENT LOCATION	4
	Show info such as: History of corner, with reference to Vol.	
	and pg., dates, surveyor; exact description of monument	L_i_L_iX
	and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary)	LOCATION (Indicated by 'X')
	No record of any resurveys. Any monument	SEAL:
	obviously gone due to ditching. Ran EDM T-2	WILL CON E
	traverse of sections 1 and 12, analyzed fence an	d Single
	possession lines, compared with original notes a arrived at a location for this corner. A straigh	t ANTHONY B.
	line proration for this corner would not have fi	
	any possession lines at all.	Wisconsin Rapids,
		Wis.
)k	7-16-84 MK-DK	A DO THE SHAPE
		Constitution of the second
		1
		DATA SHOWN HERE ON CERTIFIED CORRECT:
		Registered Land Surveyor
		DATE: 1/5/81
	THE CVETCH	CCESS FROM THE NORTH OFF HWY 73
	TIE SKETCH	THROUGH CRANBERRY FARM
	Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to	The state of the s
	arrive at corner. 22" OAK/BT	FALL MA
	TO TEST VILLE	0. 11
4"	IP SET ON LINE TO	2 OPEN " (IE).
4" Tale	ESS CAPS WITH A	on coper in
4" Tale 6 (IP SET ON LINE HO OF SET ON LINE HO OF N 58°31'04" W OF EAST SECTION OF EAST SECTION	or coper in
u" Talo Go (IP SET ON LINE HO ESS CAPS WITH A OF N 58°31'04"W ON OF EAST SECTION ORING OF S 1°06'40"E	Registered Lind Surveyor DATE: 1/5/81 CCESS FROM THE NORTH OFF HWY 73 THROUGH CRANGERBY FARM FRUTANIA FRUTANIA ON CREEK ON CREEK
4" Tale 6 (IP SET ON LINE HO ESS CAPS WITH A OF N 58°31'04"W ON OF EAST SECTION ORING OF S 1°06'40"E	on coper in
Talo Talo Gatro BEA	1RING OF 5 1°06'40'E	<u> </u>
Talo Talo Gatro BEA	IP SET ON LINE HO ESS CAPS WITH A OF N 58°31'04" W ON OF EAST SECTION PRING OF S 1°06'40" E ISCS IN TREES	8't DITCH &
Talo Talo Gatro BEA	1RING OF 5 1°06'40'E	8't DITCH & NIZH TP 46.98' D MORK BT
Talo Talo GTIC BEA	ISCS IN TREES	8'± DITCH & 124 TP 46.98' D 14'0AK'BT
ur Tale Gotte BEA	ISCS IN TREES	8't DITCH & OF THE BY SER. 3143 D 14' OF K BT 3.43 D 22.93 D 80 N N N N N N N N N N N N N N N N N N N
ur Tale Gotte BEA	ISCS IN TREES	874 DITCH & DI
ATALO BERI	ISCS IN TREES	1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Talo Talo Gatro BEA	ISCS IN TREES	874 DITCH & DI
ATALO BERI	ISCS IN TREES	STEDNO SIGN (2. JANK PING) 12. JANK PING 13. JANK PING 14. JANK PING 14. JANK PING 15. JANK PING 16. JANK PING 16. JANK PING 17. JANK PING 18. JANK

MAINTENANCE RECORD

DATE	BY WHOM	REMARKS
5-23-89	6R - KZ	o K
15 JUNE 94	JG-CR	OK
3-1-99	JG-55	OK
6-30-04	55	NW'LY WITHESS OK - UNABLE TO CROSS
		CREEK to I SE
	·	
ł	1	<u></u>