# OT RANGE ADAMS COUNTY COUNTY CORNER NO: 39 ROMPORTOL ID: 42007112000

## PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT:

**SURVEY NAIL** 

ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 311689.743

E. 583265.994

ELEVATION-

DATUM

FIELD WORK DATE:


02/17/2020

#### **BASIS FOR MONUMENT LOCATION**

1982 - PLS 878 CORNER SET EQUIDISTANT AND ON LINE BETWEEN THE NW CORNER OF SECTION 12 AND THE SW CORNER OF SECTION 12. NO RESURVEYS OF RECORD. SEARCHED FOR BEARING TREES, NONE REMAIN. ANY OTHER EVIDENCE OF THIS CORNER DESTROYED BY DITCHING.


2013 - PLS 1478 FOUND HARRISON IN PLACE 8-16-13 AND REMOVED BECAUSE OF ROAD CONSTRUCTION AND SET IRON RODS FOR NEW TIES. SET MAG NAIL IN PLACE OF HARRISON ON 10-24-13 AFTER ROAD CONSTRUCTION COMPLETED.

2020 - PLS 2675 FOUND SURVEY NAIL IN THE ROAD SURFACE AND 4 TIES. DID NOT LOOK FOR ANY ADDITIONAL MONUMENTS BELOW SINCE THE HARRISON WAS REMOVED IN 2013 FOR ROAD CONSTRUCTION. THE MONUMENT AGREES WITH ALL 4 TIES. ACCEPTED THE SURVEY NAIL AS THE CORNER LOCATION AND MEASURED TO THE EXISTING TIES.



**LOCATION** 

(INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR ZOZO

#### -TIE SKETCH

NOTE: THE CORNER LANDS 9.4'± EAST OF CTH 'G' CENTERLINE.



FIELD MOWED AREA

- FOUND 3/4" IRON ROD
- FOUND 1-1/4" O.D. IRON PIPE
- FOUND SURVEY NAIL MONUMENT
- VINYL "T" POST

### U.S PUBLIC LAND SURVEY MONUMENT RECORD CORNER NO. 39 ADAMS COUNTY, WISCONSIN

SECTION 12 TOWN 20N RANGE 7E


TYPE OF MONUMENT: Mag Nail

ADAMS COUNTY COORDINATES: N: 311,689.780 ft

E: 583,266.055 ft

ELEVATION \_ MSL DATUM: NOT APPLICABLE

THETA ANGLE: NOT APPLICABLE FIELD BOOK: 88, PAGE 131 DRAWN BY: ERIC SCHOOT



LOCATION

#### BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pa., dates, surveyor; exact description of monument replaced if location computed, by taped or EDM traverse, landowner remarks, etc.

Corner set equidistant and on line between the NW corner of Section 12 and the SW corner of Section 12. No resurveys of record. Searched for bearing trees, none remain. Any other evidence of this corner destroyed by ditching.

- Anthony Kiedrowski, 5-25-82

Found Harrison in place 8-16-13 and removed because of road construction and set Iron Rods for new ties. Set mag nail in place of Harrison on 10-24-13 after road construction completed.



DATA SHOWN HEREON CERTIFIED CORRECT:

REGISTERED LAND SURVEYOR DATE: 2 December, 2013

TIE SKETCH: 1 Inch = 30 Feet ■8° 3/4" Iron Rod 3/4" Iron Rod WWDND Sign w/DND Sign @ on T-Post on T-Post 3/4" Iron Rod 456° 1" Iron Pipe MAINTENANCE RECORD w/DND Sign W w/cap w/DND DATE INIT. | REMARKS H.H Sign on T-Post on T-Post  $\dot{\circ}$