# ADAMS COUNTY COUNTY CORNER NO: 75 ROMPORTOL ID: 41807192000

# PUBLIC LAND SURVEY MONUMENT RECORD

**HARRISON** TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 237721.847

E. 562263.061


**ELEVATION-**DATUM

FIELD WORK DATE: 01/13/2020


#### BASIS FOR MONUMENT LOCATION

1981 - PLS 1478 SEARCH AREA FOR THIS CORNER WAS DETERMINED BY MEASURING RECORD DISTANCE NORTH FROM THE CREEK NOTED IN THE ORIGINAL NOTES AS 30.50 CHAINS NORTH OF THE SW CORNER OF SECTION 20. AT THIS LOCATION BITS OF FENCE WIRE FOUND RUNNING IN A SOUTHERLY DIRECTION FROM THE NORTHEAST CORNER OF A GROWN OVER FIELD AND IN A CLUMP OF BLACK OAK TREES THAT FIT THE ORIGINAL BEARING AND DISTANCE (5" BLACK OAK, S89°E 14 LINKS, 9.24'). THESE TREES APPEAR TO HAVE SUCKERED FROM THE ORIGINAL BEARING TREE THAT WAS DESTROYED BY FIRE AS WITNESSED BY LARGER FIRE SCARRED TREES IN THE IMMEDIATE VICINITY. THE CORNER WAS LOCATED AT RECORD BEARING AND DISTANCE FROM THIS CLUMP OF BLACK OAK TREES. EDM/TRANSIT TRAVERSE OF SECTIONS 19 AND 20 VERIFIES THIS LOCATION.

2020 - PLS 2675 FOUND HARRISON MONUMENT FLUSH WITH THE GROUND AND 4 WITNESS TREES. THE MONUMENT AGREES WITH ALL WITNESS TREES. ACCEPTED THE HARRISON MONUMENT AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE EXISTING WITNESS TREES.



LOCATION (INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

#### -TIE SKETCH

NOTE: THE WITNESS TREE TO THE SW IS S29°W, 6'± FROM THE HARRISON MONUMENT.



N21°E N47° 24' 07"W 22'+/-44.41 N37° 59' 59"E 39.30' MIXED WOODS N49°W 16'+/-

- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- FOUND HARRISON MONUMENT
- STEEL FENCE POST
- VINYL "T" POST
- WITNESS TREE

# **Government Land Corner Certificate**


ADAMS	County
TYPE OF MONUMENT: HARRISON	V STANDARD
STATE PLANE COORDINATES: N_	
<u>E_</u>	
ELEVATION — M.S.L. DATUM:	
THETA ANGLE:	**************************************
FIELD BOOK: A-F 3	PAGE <i>52</i>
DRAWN BY: S. SORENSEN	
	<del></del>

## BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary)

A search area for this corner was determined by measuring record distance North from the creek noted in the original notes as 30.50 chains north of the SW corner of section 20. At this location bits of fence wire found running in a southerly direction from the northeast corner of a grown over field and in a clump of black oak trees that fit the orignal bearing and distance (5" black oak, S89°E 14 links, 9.24') These trees appear to have suckered from the original bearing tree that was destroyed by fire as witnessed by larger fire scarred trees in the immediate vicinity. The corner was located at record bearing and distance from this clump of black oak trees. EDM-Transit traverse of Sections 19 and 20 verifies this location.

CORNER NO. SECTION TOWN RANGE



(Indicated by 'X')

SEAL:



DATA SHOWN HERE ON

CERTIFIED CORRECT:

Registered Surveyor

2-24-81 DATE:

## TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.

STEEL POST I't N.W. of MARRISO 6"BLK OAK ( \$ 78.40.

53.86

Pinel87

MAINTENANCE RECORD

Date Remarks Init. TOP BROKEN PK.SS O.K. *5*-17-82 2-18-87 OK 4-21-97 16-55 1-08-02 J6 1-GONE. I-NEW IC, MON. OK 10-3-07 02-29-12 55

BT/OND

REVISED 1977

