

# CERTIFICATE OF SURVEY.


STATE OF WISCONSIN, ss. Hugh C. Hurley Surveyor, in and for the County and State aforesaid, do

hereby certify that I have surveyed and subdivided Section 5 Township 20 North of Range 7 East of Principal Meridian, as represented by the courses and distances on the following plat, and annexed field-notes of survey:

Established the center of the section at the point of intersection of straight quarter lines.

Established all quarter-quarter corners upon the section boundary at proportional distances between known section and quarter section corners, according to the original field-notes of the Government survey.

Established all lost corners at proportionate distances between known corners, according to original field-notes of the Government survey:



Plat of Section 5, Township 20 North, Range 7 East of 4 Principal Meridian. Scale, 80 chains to 6 inches. The figures in red ink are the lengths of the lines as stated in the field-notes of the Government survey.

Declination of the Magnetic Meridian from the True Meridian \_\_\_\_\_ East.

Surveyed and subdivided October 3, 4, 5 A. D. 1904, in accordance with the State Laws and Instructions of the Commissioner of the General Land Office, and recorded on pages \_\_\_\_\_ of Register in the County Surveyor's office.

WITNESS my hand this 5 day of October A. D. 1904.

Hugh C. Hurley Surveyor.

*W. E. Spiller  
Burlington*

*I survey and certify that the above is a true and correct copy of the original field notes of the survey made by me on the 3, 4, 5 days of October A. D. 1904.*

M1505200700003

DESCRIPTION of Section, Quarter Section and Quarter quarter Section Corners of Section  
 Township \_\_\_\_\_ North, Range \_\_\_\_\_ East of \_\_\_\_\_ Principal Meridian.

N. B. - The variation of needle adopted in establishing corners is \_\_\_\_\_

No.	Government Corners.	Bearing Trees.	In. dia.	Courses they bear.	Links Distant.	Bearing Trees.	In. dia.	Courses they bear.	Links Distant.
1	N. W. Sec. cor. Identified								
2	N. E. Sec. cor. Identified	B. Pine	8	S 68 E	276				
3	S. E. Sec. cor. Identified								
4	S. W. Sec. cor. Identified								
5	N. 1/4 Sec. cor. Identified								
6	E. 1/4 Sec. cor. Identified	White Pine	10	S 56 E	105				
7	S. 1/4 Sec. cor. Identified								
8	W. 1/4 Sec. cor. Identified								
<b>NO. SUBDIVISION CORNERS.</b>									
1	Center 1/4 Sec. cor.								
2	North 1/4-1/4s N. W. qr.								
3	East 1/4-1/4s N. W. qr.								
4	South 1/4-1/4s N. W. qr.								
5	West 1/4-1/4s N. W. qr.								
6	Center 1/4-1/4s N. W. qr.								
7	North 1/4-1/4s N. E. qr.								
8	East 1/4-1/4s N. E. qr.								
9	South 1/4-1/4s N. E. qr.								
10	Center 1/4-1/4s N. E. qr.								
11	East 1/4-1/4s S. E. qr.								
12	South 1/4-1/4s S. E. qr.								
13	West 1/4-1/4s S. E. qr.								
14	Center 1/4-1/4s S. E. qr.								
15	South 1/4-1/4s S. W. qr.								
16	West 1/4-1/4s S. W. qr.								
17	Center 1/4-1/4s S. W. qr.								

NAMES OF SWORN ASSISTANTS.

CHAINMEN.	FLAGMEN.	AXMEN.
W. E. Skelley B. Wilson Harrison	Arthur S. Smith	Feld Miller

MINUTES.

I surveyed Section 5 as shown by plat and could not find any of the original bearings I commenced at a stone in center of highway at NW corner of Sect 20-7 and run E. On a variation of 4.30. 33.94 chains and put in a stone thence E. 40.00 chs. and put in stone could not find any bearings nor any thing to make new ones then I ran E 80.52 chs. and put in stake bet 4 and 6. and made bearings as shown above then I started 33.94 links from NW corner of town at stone and ran South 2610 and found a stake post in by Lathrop. thence E 40.00 chs and put in post thence South 60 chs thence W 20.00 chs. thence S. 20.00 chs put in post could not find any thing of old bearings thence E. 80.52 and put in post thence N. 102.06 chs to NE corner of 20-5-7

M 1505 200700003