24 SECTION

OB ADAMS COUNTY

COUNTY CORNER NO: 80

ROMPORTOL ID: 41406242000

PUBLIC LAND SURVEY MONUMENT RECORD


TYPE OF MONUMENT: HARRIS ADAMS COUNTY COORDINATES, NAD 83 (2007) **HARRISON** N. **114082.413** E. 557550.109 **ELEVATION-**DATUM - -09/14/2017 FIELD WORK DATE:

BASIS FOR MONUMENT LOCATION


1975 - PLS 922 FOUND A RAILROAD SPIKE USED BY DEAN JESSE AND DAVE CLARK IN PRIOR SURVEYS THAT FIT TRANSIT TAPE TRAVERSE OF THE SECTION GOOD. CHECKED COUNTY SURVEY RECORDS AND NO PRIOR RESURVEYS WERE ON FILE. SET A 30" HARRISON MONUMENT AT THE CORNER LOCATION AND TIED OUT.

1999 - PLS 1397 EXISTING MONUMENT WAS FOUND AT THE CORNER LOCATION. MONUMENT WAS REMOVED AND RAISED DUE TO RECONSTRUCTION OF C.T.H. B. CORNER WAS RE-TIED.

2017 - PLS 2994 FOUND A HARRISON MONUMENT 8" BELOW THE ROAD SURFACE, 2 TIES AND 1 PROPERTY IRON. THE MONUMENT AGREES WITH THE EXISTING TIES. ACCEPTED THE HARRISON MONUMENT AS THE CORNER LOCATION. SET 4 NEW TIES AND RE-MEASURED TO ALL TIES AND PROPERTY IRON.



LOCATION (INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

FIELD

DATE

- TIE SKETCH



3/4" x 18" IRON REBAR SET, 1.50#/FT

FIELD

S 86°47'22

PK NAIL FOUND 🕀 HARRISON FOUND

3/4" IRON ROD FOUND

→ VINYL "T" POST

762 ADAMS COUNTY CORNER NO. 19 SECTION Survey Monument Record 14N TYPE OF MONUMENT: 30" HARRISON MARKER TOWN 7E RANGE STATE PLANE COORDINATES: N. E. ELEVATION - M.S.L. DATUM: ___ THETA ANGLE: __ ______ PAGE ___ FIELD BOOK: _____ BASIS FOR MONUMENT LOCATION (Use reverse side if necessary) LOCATION Show info such as: History of corner, with reference to Vol. and pg. dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner (Indicated by X') SEAL: remarks, etc. Existing Monument was found in place. Monument was removed and raised due to reconstruction of C.T.H. "B". All tie DENNIS J. measurements are horizontal measurements RUSSELL unless noted otherwise. S-1397 2- NEW TIES 1-19-86- JG 2-25-11 OK 55 MADISON, SURV MALINIAN SURV CERTIFIED CORREC DATE: TIE SKETCH ALL MEASUREMENTS ARE HORIZONTAL. (Show at least four ties) 3/4" REBAR IN DITCH LINE PK ON NORTH END OF 15" CMP C CTH P 56.15 162,151 NE COR ELEC. BOX PK ON WEST END OF 12" CMP 0

PK ON SOUTH END OF 15" CMP

001411111111111111111111111111111111111
corner no. $\frac{76 2^{(74)}}{\text{SECTION}}$
TOWN
RANGE 7-E
1
=
LOCATION (Indicated by 'X') SEAL:
CERTIFIED CORRECT: Treben W. Zietbur
Registered Land Surveyor DATE:
DATE:
4
-