


ADAMS COUNTY  
Survey Monument Record

CORNER NO. 37  
 SECTION 9  
 TOWN 16  
 RANGE 5

TYPE OF MONUMENT: HARRISON  
 STATE PLANE COORDINATES: N \_\_\_\_\_  
 E \_\_\_\_\_  
 ELEVATION — M.S.L. DATUM: \_\_\_\_\_  
 THETA ANGLE: \_\_\_\_\_  
 FIELD BOOK: 38 PAGE 13



LOCATION  
 (Indicated by 'X')

BASIS FOR MONUMENT LOCATION

(Use reverse side if necessary)

Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc.

Ran EDM/T2 traverse around Sections 8, 9, 10, 11, and 12 to determine search areas for investigation.


Excavation with backhoe by A. B. Kiedrowski, Adams County Surveyor, yielded no evidence of the original corner or any remonumentation.

Relocated corner after analysis of the field measurements, original survey notes and resurvey notes by Williams in 1871. Fencelines fit very well, as do roads.

Set Harrison on 9-7-76.

CORNER OK KV-SK 10/1180  
 ALL OK 4/15/85 O.K.  
 ALL OK 8-29-90 GR-JG  
 " " 1-11-95 JG-SS

SEAL:



CERTIFIED CORRECT:

*Dale C Hagen*  
 Registered Land Surveyor  
 DATE: 7-5-77

ALL OK 2-10-00 T.W. S.S.  
TIE SKETCH 3 GOOD TIES RE-SURVEYED  
 (Show at least four ties) 3-3-05 JS-SS  
 1 NEW TIE-10-26-10 SS

