

PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT: HARRISON (BROKEN-TOP)
 ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 185934.115

E. 512525.335


ELEVATION- _____ DATUM _____

FIELD WORK DATE: 01/13/2021

BASIS FOR MONUMENT LOCATION

1978 - PLS 1478 SET EQUIDISTANT BETWEEN ADJACENT SECTION CORNERS, BUT NOT ON A STRAIGHT LINE BETWEEN THE ADJACENT SECTION CORNERS. MEASUREMENTS TO POSSESSION LINES TO THE SOUTH INDICATED THAT THE CORNER SHOULD BE ON THE CENTERLINE OF EDGEWOOD AVENUE. EXCAVATION WITH BACKHOE BY A.B. KIEDROWSKI YIELDED NO EVIDENCE OF THE ORIGINAL MONUMENT OR ANY SUBSEQUENT MONUMENTATION.

2021 - PLS 2675 FOUND A HARRISON (BROKEN-TOP) MONUMENT 6"± BELOW THE GROUND SURFACE AND DID NOT RECOVER ANY EXISTING TIES OR WITNESSES. ACCEPTED THE HARRISON (BROKEN-TOP) AS THE CORNER LOCATION AND SET 4 NEW TIES.



LOCATION

(INDICATE CORNER BY "X")

SEAL:




DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.


PROFESSIONAL LAND SURVEYOR

DATE 2/23/2021

TIE SKETCH



- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- ⊕ FOUND HARRISON (BROKEN-TOP) MONUMENT
- VINYL "T" POST




Government Land Corner Certificate

ADAMS County

CORNER NO. 48
 SECTION 10
 TOWN 16 N.
 RANGE 5 E

TYPE OF MONUMENT: 7" X 24" IRON PIPE Harrison Set
 STATE PLANE COORDINATES: N _____
 E _____

ELEVATION — M.S.L. DATUM: _____
 THETA ANGLE: _____
 FIELD BOOK: 54 PAGE 49
 DRAWN BY: J. S. KEDROWSKI



LOCATION
(Indicated by 'X')

BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary)

Set equidistant between adjacent section corners, but not on a straight line between the adjacent section corners. Measurements to possession lines to the south indicated that the corner should be on the centerline of Edgewood Avenue. Excavation with backhoe by A.B. Kiedrowski yielded no evidence of the original monument or any subsequent monumentation.

SEAL:




DATA SHOWN HERE ON CERTIFIED CORRECT:

Gregory P Rhinehart
 Registered Land Surveyor

DATE: 12-22-78

TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.



MAINTENANCE RECORD

Date	Init.	Remarks
10/3/80	KV-SK	COR. OK
4/15/85	AK	ALL OK
2-8-90	KZ	1 GONE, NO NEW
2-7-95	JG	ALL OK
2-10-00	T.W.SS	ALL OK
3-3-05	SS/JS	2 NEW
7-7-10	SS	OK