08 SECTION

05 ADAMS COUNTY COUNTY CORNER NO: 45 ROMPORTOL ID: 41805080000

PUBLIC LAND SURVEY MONUMENT RECORD


SURVEY NAIL TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007) N. 245215.278 E. 504643.239 **ELEVATION-**DATUM 10/22/2018 FIELD WORK DATE:

BASIS FOR MONUMENT LOCATION


1974 - PLS 1103 RAN TRAVERSE OF SECTION 9 AND TIES IN TO ALL EXISTING FIELD EVIDENCE. THE CORNER FALLS IN THE MIDDLE OF STH 21 SO NO EXCAVATION WAS ATTEMPTED. MONUMENTED CORNER USING OLD FIELD NOTES, HIGHWAY RIGHT OF WAY PLANS AND FIELD EVIDENCE ANALYSIS. COULD NOT SET A HARRISON MONUMENT, SO A RAILROAD SPIKE WAS SET IN THE PAVEMENT, WHICH OVERLIES AN OLDER CONCRETE PAVEMENT. TIED OUT CORNER.

1982 - WISDOT FOUND THE RAILROAD SPIKE AND SET 4 BERNSTEN MONUMENTS.

2018 - PLS 2675 FOUND NO EVIDENCE OF THE RAILROAD SPIKE IN THE ROAD SURFACE BUT ALL 4 OF THE TIES PER TIE SHEET 10-20-1982 PER WISDOT PROJECT 6160-07-73. THE TIES ALL FIT WELL WITH EACH OTHER EXCEPT FOR THE NE TIE. COMPUTED THE CORNER LOCATION FROM THE NW, SW AND SE TIES. SET A SURVEY NAIL IN THE ROAD SURFACE AT THE COMPUTED LOCATION AND RE-MEASURED TO THE EXISTING TIES.



(INDICATE CORNER BY "X")





DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

-TIE SKETCH

NOTE: THE CORNER FALLS 1'± WEST OF THE CENTERLINE OF 18TH AVE AND 0.5'± NORTH OF THE CENTERLINE OF STH 21.





FOUND WISDOT ALUMINUM BERNSTEN CAP

RE-SET SURVEY NAIL

RIGHT-OF-WAY GUARD POST

CORNER NO. __ ADAMS COUNTY SECTION Survey Monument Record TOWN TYPE OF MONUMENT: Railroad Spike Z.00' P.K. NAIL TIES RANGE STATE PLANE COORDINATES: N. ELEVATION - M.S.L. DATUM: _ THETA ANGLE: _ FIELD BOOK: _____ PAGE BASIS FOR MONUMENT LOCATION (Use reverse side if necessary) LOCATION Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner DALE C. HAGEN S-1103 Wisconsin 7 remarks, etc. Ran traverse of Section 9 and ties in to all existing field evidence. Corners falls in middle of S.T.H 21 so no excavation was attemted. Monumented corner using old field notes, highway right of way plans and field evidence analysis. Could not set Harrison Monument, so a railroad spike was set in pavement, which overlies an older concrete pavement. CERTIFIED CORRECT: RN-SS 11-17-78 OK GR-55 Z GONE- HOD 2 3-1-83 8-21-92 JG-B5 OK Registered Land Spireyor OK, SEE ATTACHED SHEET, I-5-98-JG DATE: July 45E D.O.T. TIE SHEET 2-5-03- JG TIE SKETCH 11 11 11 12-13-01-56 (Show at least four ties) GONE NOTE: TELEPHONE POLE GONE Ties in telephone poles TELEPHONE to nail in disc. C STATE HIGH WAY 21"

RIBHT of

WAY MARKER

Δ

R.O. W. MARKER

REVISED 1974

Title

RECORD AND CERTIFICATION OF U.S.

Signature Registered Land Surveyor

716-72		.TION					
04 Project 1. D. 6160	- 07- 73	Located by	P. J. Liép	itz			
Corner 9 Township		Range (E,W)		County Adams			
SW SECTION Wisconsin Coordinates	East (X)		North (Y)	. / 0 0 0 1 1 1 5	Elevation (2	2)	Zone
CORNER						· ·	Zone
Control Station Name	East (X)		North (Y)		Elevation (<u> </u>	2006
Horizontal - NORTH A	MERICAN, 1927	CONTROL	Vertical — M	EAN SEA LE	VEL, 1929 A	DJUSTMENT	,
Horizontal —	Order ·	SURVEY	CONTROL Vertical — _		Order		
		SKE	TCH N 89	`25'54"E	=		•
OCATION SKETCH		"36" W.	69.9 50 Po 20	th Ave, , ,) X 60.	10 E	4
Location of landmark indicated by "X") OK, 2-5-03-JG	£ STH 21.	N 00013	18 18 18 18 18 18 18 18 18 18 18 18 18 1	P 27 50"	2 / 12 / 20 / 20 / 20 / 20 / 20 / 20 / 2	98,83	1
I hereby certify 1, that I did locate R,R, Spike 1 location of such cereof, place a permanant	e the above ; I further orner I did, nent marker ; I furthe	certify that at the exac consisting o	to perpetut location	_ lcea			
	SE OF ATTURES						
	onuments			<u> </u>	SEA	1	

Registration No.