02 SECTION

19 TOWN

OT RANGE ADAMS COUNTY COUNTY CORNER NO: 30

PUBLIC LAND SURVEY MONUMENT RECORD

HARRISON TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (1907) N. 282497.000 E. 580570.136


ELEVATION- - --- DATUM

04/30/2019 FIELD WORK DATE:


BASIS FOR MONUMENT LOCATION

1975 - PLS 1103 TAN EDM/TRANSIT TRAVERSE AROUND SECTION 2 AND THE ADJACENT SECTIONS IN THE TOWN OF COLBURN. COULD FIND NO EVIDENCE OF THE ORIGINAL CORNER OR ANY REMONUMENTATION OF THE CORNER. RELOCATED CORNER ON LINE BETWEEN THE SOUTHEAST AND SOUTHWEST CORNERS OF SECTION 2 AND AT THE PROTRACTED DISTANCE USED BY L.L.LAMPERT IN HIS SURVEY IN SECTION 2.

2019 - PLS 2675 FOUND HARRISON FLUSH WITH THE GROUND SURFACE AND 2 WITNESSES. THE MONUMENT AGREES WITH BOTH WITNESSES. ACCEPTED THE HARRISON AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE EXISTING WITNESSES.



(INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

DATE

-TIE SKETCH



MIXED WOODS FIELD SET 18" DOWN MOWED AREA S54° 25' 12"E 22.23 S25°W 15'+/-TREESTAND 13'+/-FIFI D

- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- FOUND HARRISON MONUMENT
- FENCE POST WITH NAIL
- VINYL "T" POST

CORNER NO. ADAMS COUNTY SECTION Survey Monument Record TYPE OF MONUMENT: Standard Harrison TOWN RANGE STATE PLANE COORDINATES: N. E_ ELEVATION - M.S.L. DATUM: _ THETA ANGLE: ____ FIELD BOOK: _____ _ PAGE . BASIS FOR MONUMENT LOCATION (Use reverse side if necessary) LOCATION Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner SEAL: remarks, etc. Ran EDM/transit traverse around Section 2 and the adjacent sections in the Town of Colburn. Could find no evidence of the original corner or any remonumentation of the corner. Relocated corner on line between the Southeast and Southwest corners of Section 2 and at the protracted disrance used by L.L.Lampert in his survey in Section 2. CORNER 68-55 4-26-77 PK - 55 8.23.82 Z NEW TIES OK - 2-25-02 76-S5 OK, 9-24.07-76 Registered Land Survey

19

