

ADAMS COUNTY

Survey Monument Record

TYPE OF MONUMENT: Harrison


STATE PLANE COORDINATES: N \_\_\_\_\_  
E \_\_\_\_\_

ELEVATION — M.S.L. DATUM: \_\_\_\_\_

THETA ANGLE: \_\_\_\_\_

FIELD BOOK: \_\_\_\_\_ PAGE \_\_\_\_\_

CORNER NO. 30  
SECTION 2  
TOWN T 16 N  
RANGE R 6 E



LOCATION  
(Indicated by 'X')

SEAL:



BASIS FOR MONUMENT LOCATION

(Use reverse side if necessary)

Show info such as: History of corner, with reference to Vol. and pg. dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc.

excavation by hand in known general area of corner yielded no evidence of original monument

set monument at location of 1/4 inch iron pipe which was found on an earlier survey in the section

TOP 12" BROKEN 10/15/80 KV-RN  
" " 10-31-85 MB-SS  
OK 1-9-90 KR-KZ  
ALL OK 1/23/95 JG-GR

\* (SEE REVERSE SIDE)

CERTIFIED CORRECT:

Richard G. Millman  
Registered Land Surveyor

DATE: DEC. 176

TIE SKETCH

(Show at least four ties)

NOTE: Ties in trees to nail in disc.

