OT ADAMS COUNTY COUNTY CORNER NO: 95

ROMPORTOL ID: 41607302000


PUBLIC LAND SURVEY MONUMENT RECORD

HARRISON (BROKEN-TOP) TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007) N. 172657.304 E. 562734.714 - - DATUM_ **ELEVATION-_** 10/06/2020 FIELD WORK DATE:

BASIS FOR MONUMENT LOCATION

1974 - PLS 878 SET ON A STRAIGHT LINE EQUIDISTANT BETWEEN SECTION CORNERS. EXCAVATED AREA WITH BACKHOE- FOUND NOTHING.

2020 - PLS 2675 FOUND HARRISON (BROKEN-TOP) 8"± BELOW THE ROAD SURFACE AND 1 TIE. THE MONUMENT AGREES WITH THE EXISTING TIE. ACCEPTED THE HARRISON (BROKEN-TOP) AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE EXISTING TIE.



LOCATION (INDICATE CORNER BY "X")

SEAL: CONS KEVIN C. BOYER

DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

SURV

PROFESSIONAL LAND SURVEYOR

-TIE SKETCH

NOTE: THE CORNER LANDS .5'± WEST OF 6TH AVE. CENTERLINE.



FIELD N87° 39' 38"E 26,43 FIELD

FIELD

- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- FOUND 2-3/8" O.D. IRON PIPE
- FOUND HARRISON (BROKEN-TOP) MONUMENT
- STEEL FENCE POST
- VINYL "T" POST

ADAMS COUNTY

Survey Monument Record

TYPE OF MONUMENT: Hairison Standard STATE PLANE COORDINATES: N__

 \mathbf{E}_{-}

ELEVATION - M.S.L. DATUM: ___ THETA ANGLE: _

FIELD BOOK: ______ PAGE _____


BASIS FOR MONUMENT LOCATION

(Use reverse side if necessary)

Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc.

Set on a straight line equidistant between section corners. Excavated area with backhoe-found nothing.

CORNER GR-55 O.K. 2-22-77 3-22-82 6R-55 12-9-86 11 12-26-91 KZ-62 1-15/97 JG-55 1-03-02 Mh. 1-30-07 JG-SS OK 01-18-12 MS



SEAL:



CERTIFIED CORRECT: cochocosh Registered Land Surveyor 6/12/74 DATE: .

TIE SKETCH

(Show at least four ties)

REAL STREET

Ties are to mail and disc.

Bwer Q Ble (1)

26.55' 0

Power Pole/Trans.