


Government Land Corner Certificate

ADAMS County
 TYPE OF MONUMENT: Harrison
 STATE PLANE COORDINATES: N _____
 E _____
 ELEVATION — M.S.L. DATUM: _____
 THETA ANGLE: _____
 FIELD BOOK: 57 PAGE 27
 DRAWN BY: Roger Nuber

CORNER NO. 38
 SECTION 11
 TOWN 17
 RANGE 5



LOCATION
 (Indicated by 'X')

BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary)

Ran EDM/T2 traverse around Section 11 and the West line of Section 14 to determine search area for investigation.

Excavation with backhoe yielded no evidence of the original corner or any remonumentation. Could find no bearing trees.

Relocated corner half way and on line between the Northwest and Southwest corners of Section 11.

Set Harrison Monument.

Top of Harrison is broken off, all ties OK
 5/28/85 D.K.

SEAL:



DATA SHOWN HERE ON
 CERTIFIED CORRECT:

Dale C Hagen
 Registered Land Surveyor

DATE: November 9, 1977

TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.

NOTE

Ties in trees to
 nail in disc.

MAINTENANCE RECORD

Date	Init.	Remarks
9/26/80	KU-SK	MON REEPS, TIES OK
1-29-90	K2-SS	OK
1-3-95	BS-SS	1 GONE - No NEW
12-3-99	JG-SS	3 NEW TIES
2-21-05	JA-JG	2 NEW TIES, 2 GONE
9-2-10	SS	UNCOVERED MON 14" DEEP SET MAG NAIL 1.0' WEST & SOUTH

