
SWM 22-14-6

## MORTGAGE INSPECTION AND DESCRIPTION

Located in part of Lot 1, CSM NO. 2847, Adams County, Wisconsin Client: Dennis Mitchell, % Wis. Dells Realty, PO Box 25, Wis. Dells WI 53965 CARLSON SURVEYING, 127 10th. Ave., Baraboo WI 53913. Tel 608-356-3816.



## DESCRIPTION FOR MORTGAGE PURPOSES ONLY:

Part of Lot 1, CSM No. 2847, Section 22, 114N, R6E, Adams County, Wisconsin bounded by the following described line: Beginning at a northwest corner of said Lot 1 on the west line of said Section 22; thence N87°21'39"E, 233.00 feet; thence N0°48'33"E, 374.00 feet; thence N87°21'39"E, 293.16 feet; thence N2°38'21"W, 68.00 feet; thence N87°21'39"E, 293.61 feet; thence S2°38'21"E, 210.80 feet; thence S58°54'16"W, 622.31 feet; thence S87°21'39"W, 299.12 feet; thence N0°48'33"E, 66.12 feet to the point of beginning. Said parcel contains 5.00 acres and is subject to highway and other easments of record.

## SURVEYORS CERTIFICATE:

I, Kenneth G. Carlson registered land surveyor, hereby certify that the improvements shown on the above map are correct to the best of my knowledge, information and belief.

NOTE: This inspection is not intended to be a survey of the property described but to be used for mortgage purposes only. Lot bearings and distances are taken from CSM No. 2847 and are not checked for accuracy.

POS22140622001