ADAMS COUNTY

TYPE OF MONUMENT: ___

Survey Monument Record

STATE PLANE COORDINATES: N.

ELEVATION - M.S.L. DATUM: _

CENTER OF SECTION

CORNER NO.

SECTION 9

RANGE 5

*

LOCATION

(Indicated by 'X')

SEAL:

N

BASIS FOR MONUMENT LOCATION

38

(Use reverse side if necessary)

THETA ANGLE: __

FIELD BOOK: ___

Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc.

Ran EDM/T2 traverse around Southern half of Sections 8 and 9, and Sections 10, 11, and 12 to determine search areas for investigation and taped to North Quarter corner of Section 9.

1" x 30" 1.P. 1.68 LBS/FT.

Found remains of fence posts at intersection of very ancient fence lines to the East and South.

Could find no other evidence of the corner as set by County Surveyor J.S. Williams on September 6 and 7, 1871, as recorded in the loose leaf County Surveyor notes. This location matches the dimensions of Williams as close as can.

Found series of pipe from 16 feet North of Center of Section toward North Quarter corner, Registered Land Surveyor but none are of record.

DATE: November

DALE C.
HAGEN
9-1103
Wissonsin Replis,
Wis.

CERTIFIED CORRECT:

Registered Land Surveyor

DATE: November 30, 1976

TIE SKETCH_	NOTE:	
(Show at least four ties)	Ties in trees to nail in disc.	
4"BLACK (M) OAK (BT) EXISTING 134"(OD) IRON PIDE Y (BT) OF UNKNOWN ORIGIN (BT)		Й
34'±	26.18' 26.18' X X X X X X X X X X X X X	_
SWAMP	Signature of the state of the s	
REVISED 1974 M150916050000		