

ADAMS COUNTY

Survey Monument Record

TYPE OF MONUMENT: RR Spike in Bituminous

STATE PLANE COORDINATES: N _____
E _____

ELEVATION — M.S.L. DATUM: _____

THETA ANGLE: _____


FIELD BOOK: _____ PAGE _____

CORNER NO. _____

SECTION 34

TOWN 16 N

RANGE 7 E



LOCATION
(Indicated by 'X')


SEAL:

BASIS FOR MONUMENT LOCATION

(Use reverse side if necessary)

Show info such as: History of corner, with reference to Vol. and pg. dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc.

Re-established from existing evidence in and around the Village of Brooks, and by using the survey notes on Page 120 of Volume 1 of the Survey Records in the County Surveyor's Office, as done by M.C.Smith, Adams County Surveyor of April 25, 1910.



CERTIFIED CORRECT:

Dale C. Hagen
Registered Land Surveyor

DATE: 6/3/75

TIE SKETCH

(Show at least four ties)

