

COUNTY SURVEYOR

In and For

ADAMS COUNTY.

A. J. BARRETT, County Surveyor,
Plainville, Wis.M. C. SMITH, Deputy,
Friendship, Wis.

July 8

Plainville, Wis.

1901

Town 19 R 5 E, Sec 28 - Kantersal
 Started at S E corner of 28 Ran west at 6 1/2 V
 Distance 80 chains & 45 links found one Bearing
 missed Post 6 links to the North must move
 first 80 Rod Post 11 1/4 links west & 1 1/2 north and 1/4
 Post 22 1/2 west & 3 north second 80 Rod Post
 33 west & 4 1/2 north. Then Ran North on west
 side of 28 to 1/4 Post Distance 40 chains missed
 1/4 Post 14 links to the West, must move 80 Rod Post
 south of quarter post 7 links East, Then Ran North
 at 7 V to NW corner of 28 Distance 40 chains
 & 17 links missed Post, found Bearings & Post, 48
 links to the west, must move 80 Rod Post 22 1/2 links
 east, & 8 1/2 links North, Then Ran East on North
 line of said sec at 6 V found 1/4 Post on North side
 of section Distance 40 chains & 35 links, missed Post 13
 links to the North, must move 80 Rod Post 17 1/2 links
 East & 6 1/2 south, Then ran east at 6 V, to section
 corner found stone Distance 40 chains & 32 links
 missed Post 7 links to the North, must move 80
 Rod Post 16 links East & 3 1/2 North,

MIS28190500002

10-6-5

on Book Page - 12

45-
67
112

12

from Ran North on East side of section at 92
 N, found no 1/4 part or bearings distance 80 chains
 & 25 links, marked A & corner of section 92 links
 to the east. must move first 80 Rod part from
 North 23 links West & 6 links south, must move 1/4 part
 4 1/2 West & 12 1/2 south, must move second 80 Rod
 part 69 links West & 18 links south.
 Made corrections on south side of section
 from Ran North on 1/4 link from south 1/4 part to North
 1/4 part moved 1/4 part on North side 18 links to
 the west. must move 80 Rod part from North 10 East
 & 6 links North, North Rod 4 North & 1 1/2 East 80 Rod part
 from North 2 North & 3 1/4 East.