O4 ADAMS COUNTY CORNER NO: 69 ROMPORTOLID: 41804150

ROMPORTOL ID: 41804150000

PUBLIC LAND SURVEY MONUMENT RECORD


HARRISON TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007) N. 239952.507 E. 484222.053 DATUM **ELEVATION-_** 01/16/2019 FIELD WORK DATE:_

BASIS FOR MONUMENT LOCATION


1981 - PLS-584 TRAVERSED AREA TO LOCATE AREA TO BE SEARCHED FOR EVIDENCE OF ORIGINAL CORNER OR REMONUMENTED CORNER. THE SEARCH FAILED TO TURN UP ANY EVIDENCE. AFTER ANALYZING THE TRAVERSE DATA, INCLUDING FENCE LINES.

2013 - PLS-1478 REDREW THE TIE-SHEET

2019 - PLS-2675 FOUND HARRISON MONUMENT FLUSH WITH THE GROUND SURFACE AND 3 WITNESSES. THE MONUMENT AGREES WITH ALL 3 WITNESSES. ACCEPTED THE HARRISON AS THE CORNER. SET 4 NEW TIES AND MEASURED TO THE EXISTING WITNESSES.



(INDICATE CORNER BY "X")




DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

- TIE SKETCH



- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- FOUND HARRISON MONUMENT
- VINYL "T" POST
- WITNESS TREE



MIXED WOODS


MISCONSIN RIVER

Government Land Corner Certificate CORNER NO. . DAMS County SECTION TYPE OF MONUMENT: TOWN STATE PLANE COORDINATES: RANGE ELEVATION — M.S.L. DATUM: THETA ANGLE: . FIELD BOOK: . **PAGE** DRAWN BY: ___ BASIS FOR MONUMENT LOCATION Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary) LOCATION (Indicated by 'X') Traversed area to locate area to be searched SEAL: for evidence of Original corner or remonumented corner. The search failed to turn up any evidence. After analyzing the traverse data, including fence lines, the corner was located as shown. WAYNE BASLE 1167 WIS. RAPIDS AND SURVE DATA SHOWN HERE ON CERTIFIED CORRECT:

Nov. 1981

TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.



MAINTENANCE RECORD

DATE	BY WHOM	REMARKS
4-11-83	6R - 55 Ju 6R - J6	0.K.
9-8-92	Jo	O.K.
2-05-98	6R-J6	ADD 1 TIE
2-21-03	J6	OK
11-15-07	SJS	o K
•		