OA ADAMS COUNTY

COUNTY CORNER NO: 93

ROMPORTOL ID: 41804240000

PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT:	1-1/4" O.D. IRON PIPE
ADAMS COUNTY COORDINATES,	NAD 83 (2007)
N. 234747.407	

DATUM — — —

FIELD WORK DATE: 12/20/2017

E. 494666.086

BASIS FOR MONUMENT LOCATION

2013 - PLS 1478 RE-DRAFTED PRIOR TIE SHEET BY GREGORY P. RHINEHART FROM 1979. RHINEHART RAN EDM/T2 TRAVERSE OF SECTION 19-18-5 TO DETERMINE THE SEARCH AREAS. INVESTIGATION YIELDED NO EVIDENCE OF THE ORIGINAL MONUMENT OR ANY SUBSEQUENT MONUMENTATION. THE LOCATION FOR THIS CORNER WAS DETERMINED BY THE SINGLE PROPORTIONATE METHOD ON A LINE BETWEEN THE NW CORNER OF SECTION 19-18-5 AND THE W1/4 CORNER OF 30-18-5. THE EXISTING 1" IRON PIPE AT THE W1/4 CORNER OF SECTION 19 WAS NOT USED TO PROPORTION IN THE SW CORNER BECAUSE THE PIPE AT THAT LOCATION DID NOT "FIT" OTHER COLLATERAL EVIDENCE IN SECTION 19. SET A 1"X5' IRON PIPE W/CAP AND TIED OUT.

2017 - PLS 2994 FOUND A 1-1/4" O.D. IRON PIPE 6" ABOVE THE GROUND SURFACE AND 2 WITNESS TREES. THE MONUMENT AGREES WITH THE EXISTING WITNESS TREES. ACCEPTED THE 1-1/4" O.D. IRON PIPE AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE TIES AND WITNESS TREES.



LOCATION (INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

-4-18

- TIE SKETCH


NOTE 1: THE CORNER FALLS 76'± SOUTH OF THE EDGE OF WATER OF THE CREEK.

NOTE 2: FOR BEST ACCESS, PARK AT THE INTERSECTION OF 20TH AND CYPRESS AVE AND WALK NORTH TO THE CORNER.



 3/4" x 48" IRON REBAR SET, 1.50#/FT 1-1/4" O.D. IRON PIPE FOUND VINYL "T" POST

WITNESS TREE FOUND



U.S PUBLIC LAND SURVEY MONUMENT RECORD CORNER NO. 81 ADAMS COUNTY, WISCONSIN TOWN 18N

SECTION 19 TOWN 18N RANGE 5E


TYPE OF MONUMENT: 1"x5' Iron Pipe/Cap - In Swamp

STATE PLANE COORDINATES: N: NOT APPLICABLE

E: NOT APPLICABLE

ELEVATION _ MSL DATUM: NOT APPLICABLE

THETA ANGLE: NOT APPLICABLE FIELD BOOK: 54 PAGE: 49 DRAWN BY: ERIC SCHOOT



BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced if location computed, by taped or EDM traverse, landowner remarks, etc.

Ran EDM/T2 traverse of Section 19-18-5 to determine search areas. Investigation at this location yielded no evidence of the original monument nor any subsequent monumentation. The location for this corner was determined by the single proportionate method on line between the NW Cor. of 19-18-5 and the W1/4 Cor. 30-18-5. The existing 1" iron pipe at the W1/4 Cor. Sec. 19 was not used to proportion in the SW Corner because the pipe at that location (W1/4) did not "fit" other collateral evidence in Section 19.

-Gregory P. Rhinehart, 1-5-1979

THIS IS A COMPILATION AND REDRAFT OF PREVIOUS MONUMENT RECORDS.
BASIS FOR MONUMENT LOCATION IS FROM ORIGINAL REMONUMENTATION.



DATA SHOWN HEREON CERTIFIED CORRECT:

REGISTERED LAND SURVEYOR

DATE: 21 JUNE, 2013

