

10
SECTION

18
TOWN

06
RANGE

ADAMS COUNTY

COUNTY CORNER NO: 38

ROMPORTOL ID: 41806102000

PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT: HARRISON (BROKEN-TOP)
ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 247995.343

E. 546649.739


ELEVATION: _____ DATUM: _____

FIELD WORK DATE: 12/16/2019

BASIS FOR MONUMENT LOCATION

1978 - PLS 878 SET HARRISON EQUIDISTANT AND ON LINE BETWEEN ADJACENT SECTION CORNERS AFTER AN EXTENSIVE SEARCH YIELDED NO PREVIOUS MONUMENTATION.

2019 - PLS 2675 FOUND HARRISON (BROKEN-TOP) 12" BELOW THE GROUND, 1 TIE, AND 1 WITNESS. THE MONUMENT AGREES WITH THE TIE AND WITNESS. ACCEPTED THE HARRISON (BROKEN-TOP) AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE EXISTING TIE AND WITNESS.



LOCATION

(INDICATE CORNER BY "X")

SEAL:





DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

DATE 1/9/2020

TIE SKETCH

NOTE: TIES SET IN MOWED AREA ARE SET 12" BELOW GROUND SURFACE.




- SET 3/4" x 18" IRON REBAR, 1.50#/FT
- ⊙ FOUND 1-1/2" O.D. IRON PIPE
- ⊕ FOUND HARRISON (BROKEN-TOP) MONUMENT
- ~ STEEL FENCE POST
- VINYL "T" POST
- ⊙ WITNESS TREE

Government Land Corner Certificate

ADAMS County
 TYPE OF MONUMENT: HARRISON
 STATE PLANE COORDINATES: N _____
 E _____
 ELEVATION — M.S.L. DATUM: _____
 THETA ANGLE: _____
 FIELD BOOK: 57 PAGE 22
 DRAWN BY: LANCE HABECK

CORNER NO. 38
 SECTION 11
 TOWN 18 N
 RANGE 6 E



LOCATION
(Indicated by 'X')

BASIS FOR MONUMENT LOCATION

Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary)

Set monument equidistant and on line between adjacent section corners after an extensive search yielded no previous monumentation.

SEAL:



DATA SHOWN HERE ON
CERTIFIED CORRECT:


Anthony B. Kiedrowski
Registered Land Surveyor

DATE: 7/13/78

2008
OVER

TIE SKETCH

Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.



MAINTENANCE RECORD

Date	Init.	Remarks
3-14-83	GR-SS	OK
8-7-92	JG-BS	1-GONE, 2-NEW, TOP BROKEN ON MON.
3-6-98	JG	1-GONE, 4-LEFT

REPLANTED
AREA

FD HARRISON - TOP BROKEN - SET STEEL POST IMM. WEST
05-27-08 SJS

CUT OFF AREA

NORTH EDGE OF PINE
PLANTATION ± 50' NORTH

TRAIL
ENDS

PINE
PLANTATION

7" NORWAY / SIGN
'08

PLACED BROKEN
PIECES OF HARRISON
AT BASE OF TREE S.B.

5' JACK PINE / SIGN IN CUT
BETWEEN PINES AND MIXED
WOODS

FD.
JUNG
1 1/2" IP

MIXED
WOODS

9.55'

30.1'

20.94'

± 12'

'08 SET 3/4" ROD
13' E. OF 2" BIK OAK

44.0'

12" BIK OAK

E TRAIL