19 **TOWN** 

## OT RANGE ADAMS COUNTY COUNTY CORNER NO: 86

ROMPORTOL ID: 41907210020

## PUBLIC LAND SURVEY MONUMENT RECORD

2-3/8" O.D. IRON PIPE TYPE OF MONUMENT: ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 266620.071

E. 570097.693


ELEVATION-DATUM - — —

04/15/2019 FIELD WORK DATE:


## BASIS FOR MONUMENT LOCATION

1983 - PLS 1551 NO EVIDENCE OF BEARING TREES REMAINS, NO OCCUPATION IN AREA. CORNER WAS RESET PROPORTIONALLY ON A STRAIGHT LINE BETWEEN ADJACENT SECTION CORNERS.

2019 - PLS 2675 FOUND 2-3/8" O.D. IRON PIPE 12" ABOVE THE SWAMP SURFACE AND 1 WITNESS. THE MONUMENT AGREES WITH THE WITNESS. ACCEPTED THE 2-3/8" O.D. IRON PIPE AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE EXISTING WITNESS.



(INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

-TIE SKETCH



- OPEN S87° 06' 27"W \$75° 37' 19"E 20,39 SWAMP
- SET 3/4" x 48" IRON REBAR, 1.50#/FT
- FOUND 2-3/8" O.D. IRON PIPE MONUMENT
- VINYL "T" POST
- WITNESS TREE

U.S. PUBLIC LAND SURVEY MONUMENT RECOR	<u>RD</u>
ADAMS COUNTY	CORNER NO. 86
ADAMS COUNTY  TYPE OF MONUMENT: 2" 1.D. x 60" galvanized pipe	SECTION 21
STATE PLANE COORDINATES: N	TOWN 19N
E	RANGE <u>7E</u>
ELEVATION — M.S.L. DATUM:	francis o de a parameterment o de se constad
THETA ANGLE:	
FIELD BOOK: Adams County PAGE 63	
DRAWN BY: D. Riesop	21
BASIS FOR MONUMENT LOCATION	
Show info such as: History of corner, with reference to Vol. and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner remarks, etc. (Use reverse side if necessary) (in conformance with Section A-E 502 of the	LOCATION (Indicated by 'X') SEAL:
Wisconsin Administrative Code )	1
No evidence of bearing trees remains, no occupation in area.	SINGS CONSIDER
Corner was reset proportionally on a straight line between adjacent section corners.	DAVID C RIESOP S-1551 CAMECIO C C CAMECIO C C C C C C C C C C C C C C C C C C C
day of Sept. 19 19 19 19 19 19 19 19 19 19 19 19 19	DATA SHOWN HERE ON CERTIFIED CORRECT:  Registered Land Surveyor  DATE: 8/25/83
	10"WILLOW MAIL ON
TIE SKETCH  Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.  SCALE 8 1"=40'	W. SIDE
N >=	HER STON SET Z" OAK POST WITH
MAINTENANCE RECORD  Date Init. Remarks  4"WILLOW, MAIL  1-7-07 JG GPS INTO AREA UNABLE  TO LOCATE CORNER OR TIES RECORD.	SURVEY MARKER SIGN INSIDE OF PIPE
	ON M. SIDE