SECTION

OS ADAMS COUNTY

COUNTY CORNER NO: 93

ROMPORTOL ID: 42005240000


PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT: **COTTON GIN SPINDLE** ADAMS COUNTY COORDINATES, NAD 83 (2007) N. **298089.202** E. **525555.757** DATUM -- -- -**ELEVATION-**02/13/2018 FIELD WORK DATE:


BASIS FOR MONUMENT LOCATION

2015 - PLS 2452 FOUND A HARRISON MONUMENT WITH THE TOP BROKEN OFF 1'± BELOW THE GRADE OF A SAND/DIRT ROAD PER TIE SHEET BY DALE C. HAGEN, DATED, 2-1-75. FOUND THE 3/4" ROD NORTHEASTERLY OF THE HARRISON MONUMENT AND ALSO A 3/4" ROD SOUTHEASTERLY OF SAID MONUMENT. ACCEPTED THE HARRISON MONUMENT AS THE CORNER, TIED INTO THE 3/" RODS AND PLACED 2 ADDITIONAL TIES, DATE OF FIELD SURVEY & MONUMENT RECOVERY WAS SEPTEMBER 02, 2015.

2018 - PLS 2994 FOUND A COTTON GIN SPINDLE IN THE ROAD SURFACE AND 4 TIES. REMOVED THE COTTON GIN SPINDLE AND FOUND NO OTHER MONUMENTATION AS DESCRIBED IN PRIOR TIESHEETS BELOW IT. THE COTTON GIN SPINDLE AGREES WITH 3 OF THE EXISTING TIES AND THE DISTANCE TO THE E1/4 OF SECTION 25 AS SHOWN ON PRIOR TIESHEET. ACCEPTED THE COTTON GIN SPINDLE AS THE CORNER LOCATION AND RE-SET IT IN THE LOCATION IT WAS FOUND AND RE-MEASURED TO THE EXISTING TIES.



LOCATION (INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.


PROFESSIONAL LAND SURVEYOR

3-1-18 DATE

- TIE SKETCH

NOTE: THE CORNER FALLS 2'± SOUTH OF THE CENTERLINE OF ARCHER AVE.





O 3/4" IRON ROD FOUND COTTON GIN SPINDLE FOUND → VINYL "T" POST


U.S. PUBLIC LAND SURVEY MONUMENT RECORD

I N S T R U C T I O N S : This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. Public Land Survey System.

= Corner monument restored.

NORTHEAST CORNER OF SECTION 25, TOWNSHIP 20 NORTH, RANGE 05 EAST, TOWN OF ROME, ADAMS COUNTY, WISCONSIN




(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence, or any other material evidence you considered, and whether the monument was found or placed.

I found a Harrison Monument with the top broken off $1'\pm$ below grade of a sand/dirt road per tie sheet by Dale C. Hagen, dated, 2-1-75. I found the $\frac{1}{2}$ " Rod northeasterly of the Harrison Monument and also found a $\frac{3}{4}$ " Rod southeasterly of said Monument. I accepted the Harrison Monument (see picture), tied into the $\frac{3}{4}$ " Rods and placed two (2) ties all as referenced below. Date of field survey & monument recovery was September 02, 2015. Elevations provided on section corners are based upon the NAVD88 Datum.


- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron, or other equally durable material.) Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate North.











(e) Describe any material discrepancy between the location of the corner as restored or re—established and the location of that corner as previously restored or re—established by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or re—established and (1) the corner as restored or re—established, and (2) to at least 2 of the 4 witness monuments shown on the drawing in (d), above.

No known discrepancy.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Found perpetuated location.

(g&h) Was the corner re-established through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

Found perpetuated location.

(i) I, Michael S. Marty, Professional Land Surveyor No. 2452, hereby certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

By: Vierbicher Associates, Inc.
Michael S. Marty, P.L.S. No. 2452

9/22/2015 Date

vierbicher

planners engineers advisors

REEDSBURG - MADISON - PRAIRIE DU CHIEN 999 Fourier Drive, Suite 201 Madison, Wisconsin 53717 Phone: (608) 826-0532 Fax: (608) 826-0530



Affix Land Surveyor Seal

SCONS

MICHAELS.

MARTY
S-2452
NEW GLARUS,
WI

SURVE