ADAMS COUNTY COUNTY CORNER NO: 38 ROMPORTOL ID: 42006102000


PUBLIC LAND SURVEY MONUMENT RECORD

TYPE OF MONUMENT:_	HARRISON (BROKEN-TOP)			
ADAMS COUNTY COORDINATES, NAD 83 (2007)				
N. 311533.369				
E. 546441.506				
ELEVATION DATUM				
FIELD WORK DATE: 05/03/2018				


BASIS FOR MONUMENT LOCATION

1980 - PLS 841 CORNER WAS ESTABLISHED MIDWAY ON A STRAIGHT LINE BETWEEN OPPOSITE SECTION CORNERS, BY E.D.M. TRAVERSE, PER INSTRUCTIONS BY ADAMS COUNTY SURVEYOR, ANTHONY B. KIEDROWSKI, RLS 878. SET HARRISON AND TIED OUT.

2018 - PLS 2994 FOUND A HARRISON MONUMENT WITH A BROKEN-TOP 24" BELOW THE ROAD SURFACE, 1 PROPERTY IRON AND 2 WITNESS TREES. THE MONUMENT AGREES WITH THE EXISTING WITNESS TREES. ACCEPTED THE HARRISON MONUMENT WITH A BROKEN-TOP AS THE CORNER LOCATION. SET 3 NEW TIES AND MEASURED TO THE TIES AND WITNESS TREES.



(INDICATE CORNER BY "X")




DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

7-18-18 DATE

-TIE SKETCH

NOTE: THE CORNER FALLS 4'± SOUTH OF THE CENTERLINE OF CTH D AND 6'± WEST OF THE CENTERLINE OF 9TH AVE.



ADAMS County	corner no38
TYPE OF MONUMENT: PK NAIL & DISC SET. HARRISON	SECTION
STATE PLANE COORDINATES: N	TOWN ZON.
E	RANGE GE.
ELEVATION — M.S.L. DATUM:	
THETA ANGLE:	
PAGEPAGE	
DRAWIN BI: VI- POR DE	H-+++ NI
BASIS FOR MONUMENT LOCATION	
Show info such as: History of corner, with reference to Vol	j j
and pg., dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse:	LOCATION
landowner remarks, etc. (Use reverse side if necessary) SFAL.	(Indicated by 'X')
CORNER ESTABLISHED MIDWAY	- 19981811111111111111111111111111111111
ON A RIGHT-LINE BETWEEN	WILLIAM C. ROHDE S-0841 Wisconsin Rapids, Wisconsin
OPPOSITE SECTION CORNERS,	WILLIAM C.
	ROHDE
Y BY E.D.M. TRAVERSE, PER	≺∷ S-0841 ↔ Wisconsin Rapids,
PHINSTRUCTIONS BY ADAMS	Wisconsin
SURVEYOR, ANTHONY	
	S. C.
I R KIEDRAWERE PICATO T	SURVERIN
B. KIEDROWSKI, RLS 878. I DATA DATA	SHOWN HERE ON
B. KIEDROWSKI, RLS 878. I DATA CERTIF	Minister
B. KIEDROWSKI, RLS 878. I DATA CERTIF	SHOWN HERE ON FIED CORRECT:
DATA CERTIFIC PROBLES DATA CERTIFIC PROBLES DATA CERTIFIC PROBLES DATA CERTIFIC PROBLES Registers Registers	SHOWN HERE ON FIED CORRECT:
DATA WAS ASSISTED BY DANIEL CERTIF	SHOWN HERE ON FIED CORRECT:
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Ex CAUATION DONE DATE:	SHOWN HERE ON FIED CORRECT:
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Ex CAUATION DONE DATE:	SHOWN HERE ON FIED CORRECT: ed Land Surveyor
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Ex CAUATION DONE DATE:	SHOWN HERE ON FIED CORRECT: Land Surveyor 110180 BEARINGS MAGNET
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Ex CAUATION DONE DATE:	SHOWN HERE ON FIED CORRECT: ed Land Surveyor
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excapation Date: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner.	SHOWN HERE ON FIED CORRECT: LOCATION AND LOCATION SEARINGS MAGNET PENAIC PISC NW FACE
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Ex CAUATION DONE DATE:	SHOWN HERE ON FIED CORRECT: Land Surveyor 110180 BEARINGS MAGNET
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. NO Excaption Done DATE: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PK NAIL ROISC SW FACE	SHOWN HERE ON FIED CORRECT: LOCATION Ed Land Surveyor 1/10/80 BEARINGS MAGNET PKNAIC F DISC NW FACE GONE GONE
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excapation food DATA CERTIF TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees and if off road - best way to arrive at corner. PKNAIL POISC SW FACE G"N. PINE	SHOWN HERE ON FIED CORRECT: 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
B. KIEDROWSKI, RLS 878. I WAS ASSISTED BY DANIEL DATA CERTIFY OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excapation Done DATE: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PKNAIL POISC SW FACE G"N. PINE	SHOWN HERE ON FIED CORRECT: LOCAL Ed Land Surveyor 1/10/80 BEARINGS MAGNET PKNAIC PISC NW FACE GN. PINE. GONE SE COR TRANS # SP 706 1994
B. KIEDROWSKI, RLS 878. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excapation fond DATA CERTIF ALL I TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees and if off road - best way to arrive at corner. PK NAIL POISC SW FACE G"N. PINE CTH'D' CTH'D' CTH'D' DATA CERTIF DATA CERTIF DA	SHOWN HERE ON FIED CORRECT: 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
B. KIEDROWSKI, RLS 878. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excapation Done DATE: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PKNAIL POISC SW FACE G"N. PINE	SHOWN HERE ON FIED CORRECT: LOCAL Ed Land Surveyor 1/10/80 BEARINGS MAGNET PKNAIC PISC NW FACE GN. PINE. GONE SE COR TRANS # SP 706 1994
B. KIEDROWSKI, RLS 878. I WAS ASSISTED BY DANIEL DATA CERTIF OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excapation fond DATA CERTIF ALL I TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees and if off road - best way to arrive at corner. PK NAIL POISC SW FACE G"N. PINE CTH'D' CTH'D' CTH'D' DATA CERTIF DATA CERTIF DA	SHOWN HERE ON FIED CORRECT: 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL CERTIFICATION OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excaption down DATE: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PKNAIL POISC SW FACE G"N. PINE VA LINE 21/2' + 2	SHOWN HERE ON FIED CORRECT: 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL CERTIFICATION OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excaption down DATE: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PKNAIL POISC SW FACE G"N. PINE VA LINE 21/2' + 2	SHOWN HERE ON FIED CORRECT: 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
B. KIEDROWSKI, RLS B78. I WAS ASSISTED BY DANIEL CERTIFICATION OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON Register 12129179. No Excaption down DATE: TIE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PKNAIL POISC SW FACE G"N. PINE VA LINE 21/2' + 2	SHOWN HERE ON FIED CORRECT: LAND SURVEYOR 1/10/80 BEARINGS MAGNET PKNAIC PISC NW FACE C"N. PINE. GONE SE COR TRANS # SP 706 1994 BLACK-TOP PAVEMENT
B. KIEDROWSKI, RLS B78. I DATA CERTIFICATION OLSEN, OF NEKOOSA, WIS. FIELDWORK PERFORMED ON IZIZAITA. NO Excapation Done Date: THE SKETCH Show at least four ties, also fence lines, roads, topo, size and type of witness trees' and if off road - best way to arrive at corner. PK NAIL POISC SW FACE G"N. PINE Z'Z'± Z & S'± VA LINE Z'Z'± Z & S'± SOOOLU Z	SHOWN HERE ON FIED CORRECT: LAND SURVEYOR 1/10/80 BEARINGS MAGNET PKNAIC PISC NW FACE C"N. PINE. GONE SE COR TRANS # SP 706 1994 BLACK-TOP PAVEMENT

MAINTENANCE RECORD

DATE	BY WHOM	REMARKS
3/01/94	GR - 54	1 TIE
3/01/94 1-11-99 2-24-04 1-7-10	JG- JF	OK
2-24-04	J6	OK
1-7-10	SS	or
		·
		·