OT RANGE ADAMS COUNTY COUNTY CORNER NO: 108 ROMPORTOL ID: 42007270020

PUBLIC LAND SURVEY MONUMENT RECORD

HARRISON (BROKEN-TOP) TYPE OF MONUMENT:

ADAMS COUNTY COORDINATES, NAD 83 (2007)

N. 293170.380

E. 575363.193

ELEVATION-DATUM

03/02/2020 FIELD WORK DATE:

BASIS FOR MONUMENT LOCATION

1975 - PLS 1103 RAN EDM/TRANSIT TRAVERSE AROUND SECTIONS 35 AND 36 TO DETERMINE SEARCH AREAS. COULD FIND NO EVIDENCE OF THE ORIGINAL CORNER OR ANY SUBSEQUENT REMONUMENTATION, OR OF ANY ACCESSORY MONUMENTS. SET CORNER HALF WAY AND ON LINE BETWEEN ADJACENT SECTION CORNERS.


1991 - PLS 1821 FOUND MONUMENT CERTIFIED BY DALE C. HAGEN R.L.S. #1103 DATED MAY 5, 1975. RETIED MONUMENT.

2020 - PLS 2675 FOUND RAIL ROAD SPIKE IN THE ROAD SHOULDER, REMOVED AND FOUND HARRISON (BROKEN-TOP) 36"± BELOW, AND 1 WITNESS TREE. THE MONUMENT AGREES WITH THE WITNESS TREE. ACCEPTED THE HARRISON (BROKEN-TOP) AS THE CORNER LOCATION. SET 4 NEW TIES AND MEASURED TO THE EXISTING WITNESS TREE.

BRUSH



(INDICATE CORNER BY "X")



DATA SHOWN HERE ON THIS TIE SHEET IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

PROFESSIONAL LAND SURVEYOR

-TIE SKETCH

NOTE: THE CORNER LANDS 13.2'± NORTH OF CTH 'O' CENTERLINE



MIXED WOODS **'0**' **CTH** S30°E 54'+/-

MIXED WOODS

SET 3/4" x 18" IRON REBAR, 1.50#/FT

FOUND HARRISON (BROKEN-TOP) MONUMENT

VINYL "T" POST

WITNESS TREE

Government Land C	orner Certificate		(108)
		CORNER NO	653
ADAMS	County	SECTION _	34
TYPE OF MONUMENT:HA	· · ·	TOWN _	20
STATE PLANE COORDINATES:	E	RANGE _	7-E
ELEVATION — M.S.L. DATU			
THETA ANGLE:			
FIELD BOOK:	PAGE		- 4
DRAWN BY://SSer5		<u> </u>	- NI
			או
BASIS FOR MONUMENT I	LOCATION		i
Show info such as: History of corne and pg., dates, surveyor; exact d	lescription of monument	<u> </u>	لـ
replaced; if location computed, by landowner remarks, etc. (Use reverse)	taped or EDM traverse; se side if necessary)	LOCATION (Indicated by 'X')	
	fied By Dale C. Hagen	SEAL:	
R.L.S. #1103 Dated M	ay 5, 1975.	WILLIAM CONO.	
Retied Monument as s	hown below.	ARTHUM SCONO	And the second
		NORBERT L. VISSERS S-1821 BOULDER JCT. WIS. DATA SHOWN HERE ON CERTIFIED CORBECT:	
		VISSERS	W
		S-1821 BOULDER JCT.	
		Wis.	##.
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	. Ista
		SURVEY INT	, i
		DATA SHOWN HERE ON	
		CERTIFIED CORRECT:	_
OK 6-01-09 5	12	Norbert Z. W. Registered Land Surveyor	seen
OK 3-16-94 J	G-35	DATE: Jan. 17, 1	1991
CHECK SURV	ey So. HAR OK 7-6-04 53	3	
Show at least four ties, also fence i	lines, roads, topo, size		
and type of witness trees' and if o arrive at corner.	Total - best way to DEAD - STANDER		
Ties to PK nail w/alum. d	isc. 12" P.J.		
	MALL STILL GOOD		
	-12	12" P.J.	
	57 104 124 0 0 E		
	N-12 N66		
•	+1 +1 - 33.70		
		4 Aspen Road	
	\$ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		
	Fo 3/4"	•	
	Roo @	7" Ash 🖊	
	104 8 Oak 33 Sout	rn	

104 8" Oak
ONECK PORTRECENT
SURVEY SOUTH >

MAINTENANCE RECORD

DATE	BY WHOM	REMARKS
	•	
		·
	<u>, </u>	
-		

ADAMS COUNTY

Survey Monument Record

TYPE OF MONUMENT: <u>Harrison</u> Monument STATE PLANE COORDINATES: N_ E ELEVATION - M.S.L. DATUM: ___ THETA ANGLE: _ FIELD BOOK: ____ __ PAGE .

BASIS FOR MONUMENT LOCATION

(Use reverse side if necessary)


Show info such as: History of corner, with reference to Vol. and pg, dates, surveyor; exact description of monument replaced; if location computed, by taped or EDM traverse; landowner

Ran EDM/transit traverse around Sections 35 and 36 to determine search areas.

Could find no evidence of the original corner or any subsequent remonumentation, or of any accessory monuments.

Set corner half way and on line between adjacent section corners.

0k 4-30-84 SS-DK OK 3-23-79 DW-RN





CERTIFIED CORRECT:

Registered Land Surveyor DATE: May 5,

